

0743Z 08 JAN 61

ROUTING SLIP

TOP SECRET

TECH

CH/

PER

COMM

25X1

OPTION

OP IV

DB
ops
"

P/C

OPERATIONAL IMMEDIATE

R/

DIRECTOR

25X1

DPD (1-2-3-4-5-6-7-8-9-10)

OPERATIONAL IMMEDIATE

S/C (11)

IN 41870

SHG

25X1

TOR: 0857Z 08 JAN 61

25X1

1.

FORWARDS FOLLOWING CAMERA OPERATION

REPORT.

2A. MISSION 3020

1. ROLL "L" EXPOSURES 2188-2422 HAVE SPLASHES OF MOISTURE PROCESSED ON THE FILM. PROBABLE CAUSE-MOISTURE CONDENSATION.

2. ROLL "R" (A) IMAGE CUT OFF APPROX 1/8 INCH ON DATA CHAMBER SIDE. (B) TWO LIGHT LEAK STREAKS APPROX 1 INCH LONG DIRECTLY ABOVE THE LETTER "R" OF THE DATA CHAMBER. (C) FACTORY SPLICE IN EXPOSURE 1962 R

3. NO EVIDENCE OF VACUM FAILURE OR TEARS

4. ALL CREASES IN THE FILM OCCURRED DURING FILM PROCESSING AND WERE ELIMINATED AS SOON AS POSSIBLE.

5. PROCESSING DATA MISSION 3020, 3019, 3018,

DEVELOPER D-19 REVLENISHER D-19 250 CC/ MIN

PROCESSING SPEED 5 FT / MIN 68 DEGREES F.

GAMMA LOW 1.84 HIGH 2.03

CLASSIFICATION 25X1

TOP SECRET

Handwritten signatures and initials

18 Sept 86

OTHER THAN THE ISSUING OFFICE IS PROHIBITED.

Copy No.

25X1



PAGE 2

2B. MISSIONS 3018 AND 3019

1. A FEW MINOR CREASES WERE CAUSED IN THE FILM PROCESSOR.
2. NO EVIDENCE OF VACUUM FAILURE OR TEARS.
3. PROCESSING DATA SAME AS FOR MISSION 3020.

END OF MESSAGE